



NOW-Consulting AG

Bettwilerstrasse 14
CH-5614 Sarmenstorf
Tel. 041 56 667 15 67
Fax 041 56 667 15 75
info@nowcon.com
www.nowcon.com

DC-Controller Description

TowerTray

DC Controllers of LaserJet 4250 / 4350 printers with Serial Numbers up to those stated below create an extensive time gap between each sheet fed from TowerTray and reduce the throughput to less than 8 pages per minute. (LaserJet 4200/4300 printers are not affected.)

Solution:

Revised DC Controllers in LaserJet 4250 / 4350 printers allow TowerTray to work at optimal speed.

Proper F/W & DCC Revision:

Make sure your printer has a DC Controller ver.**1.027** F/W / ver.**1.028** F/W or ver.**1B** F/W when attaching TowerTray.

Upgrade:

HP plans to upgrade printers with earlier F/W and DCC on a warranty basis if a TowerTray shall be installed.

LJ4250 / 4350 Printer Serial Numbers with Proper F/W & DCC Revision for TowerTray:

CNGXB07084	And later
CNGXC05236	and later
CNGXD04229	and later
CNGXF01598	and later
CNGXG01951	and later
CNGXH04494	and later
CNGXJ02515	and later
CNHXB00908	and later
CNHXC00702	and later
CNHXD02976	and later
CNHXF05226	and later
CNHXG05391	and later
CNHXH02733	and later
CNHXJ00001	and later

- At this moment there is a compatibility issue on the stapler/stacker Q2443B. Combination with TT is not supported till further notice